

REPORT OF CHANNEL CONDITIONS 100 TO 400 FEET WIDE (ER 1130-2-3165)					PAGE 1 OF 1		
					DATE June 6, 2005		
TO: The Record				FROM: U.S. Army Corps of Engineers 26 Federal Plaza, ATTN: CENAN-OP-ST New York, NY 10278-0090			
RIVER/HARBOR NAME AND STATE: East Rockaway Inlet, After Dredge Survey					MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD		
NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (nmiles)	DEPTH (feet)			
East Rockaway Inlet	Map 180 14, 15, & 21 March 2005	250	.7	12	12.7	12.6	11.3
REMARKS: <ul style="list-style-type: none">All depths are in MLWChannel length is in nautical miles.There is a shoal developing in the right quarter channel approximately 300' south of Green Can #3.							